

Asset Optimization Summary

June 8, 2026

AO Corridor	MTP ID	Facility	From	To	Asset Optimization Description
01 - DFW Connector	FT 11.50.1	SH 121	BU 121 (Denton County Line)	Stars and Stripes Way (Tarrant County Line)	Operational Improvements
01 - DFW Connector	FT 11.50.2	SH 121	Stars and Stripes Way (Dallas County Line)	FM 2499	Operational Improvements
01 - DFW Connector	FT 11.50.3	SH 121	FM 2499	IH 635	Operational Improvements
01 - DFW Connector	FT 11.60.1	SH 121	IH 635	SH 114	Operational Improvements
01 - DFW Connector	FT 12.30.5	SH 114	Park Blvd	SH 121	Operational Improvements
01 - DFW Connector	FT 12.40.1	SH 114	SH 121 (W)	SH 121 (E)	Operational Improvements
01 - DFW Connector	FT 12.50.1	SH 114	SH 121	SH 161	Operational Improvements
01 - DFW Connector	FT 130.10.1	IH 635	SH 121	Royal Ln	Operational Improvements
02 - Gateway Horizon	FT 38.20.3	US 67	Belt Line Road	Lake Ridge Parkway (Ellis County Line)	Operational Improvements, Bottleneck Removal
02 - Gateway Horizon	FT 38.30.1	US 67	Lake Ridge Parkway (Dallas County Line)	US 287	Operational Improvements, Bottleneck Removal
03 - IH 20 (Tarrant County)	FT 30.20.2	IH 20	East of IH 30 (Parker County Line)	IH 820	Operational Improvements
03 - IH 20 (Tarrant County)	FT 30.30.2	IH 20	SH 183	IH 35W	Operational Improvements, Bottleneck Removal
03 - IH 20 (Tarrant County)	FT 30.40.1	IH 20	IH 35W	Forest Hill Drive	Operational Improvements, Bottleneck Removal
04 - IH 20 (Dallas County)	FT 30.80.4	IH 20	Spur 408	Cedar Ridge Drive	Operational Improvements, Bottleneck Removal
04 - IH 20 (Dallas County)	FT 30.80.5	IH 20	Cedar Ridge Drive	US 67	Operational Improvements, Bottleneck Removal
04 - IH 20 (Dallas County)	FT 30.80.7	IH 20	Polk Street	IH 35E	Operational Improvements, Bottleneck Removal
04 - IH 20 (Dallas County)	FT 30.80.8	IH 20	IH 35E	SH 342	Operational Improvements, Bottleneck Removal
04 - IH 20 (Dallas County)	FT 30.80.9	IH 20	SH 342	Bonnie View Road	Operational Improvements
04 - IH 20 (Dallas County)	FT 30.80.10	IH 20	Bonnie View Road	IH 45	Operational Improvements
04 - IH 20 (Dallas County)	FT 30.80.11	IH 20	IH 45	St Augustine Drive	Addition of Frontage Roads, Operational Improvements
04 - IH 20 (Dallas County)	FT 30.90.3	IH 20	Seagoville Road	SH 190/State Loop 9 (Kaufman County Line)	Addition of Frontage Lanes
05 - IH 20 (Kaufman County)	FT 30.100.1	IH 20	SH 190/State Loop 9 (Dallas County Line)	FM 740	Addition of Frontage Roads, Operational Improvements, Bottleneck Removal
05 - IH 20 (Kaufman County)	FT 30.100.2	IH 20	FM 740	Spur 557	Addition of Frontage Roads, Operational Improvements, Bottleneck Removal
05 - IH 20 (Kaufman County)	FT 30.110.1	IH 20	Spur 557	Wilson Road	Addition of Frontage Roads, Operational Improvements, Bottleneck Removal
06 - IH 30 West Freeway	FT 28.10.1	IH 30	IH 20	East of IH 20 (Tarrant County Line)	Operational Improvements

NOTE: Asset Optimization improvements are typically low-cost improvements implemented prior to, or in lieu of, ultimate capacity improvement. These types of improvements are targeted to address location-specific operation, safety, and bottleneck issues within the corridor, and do not affect Transportation Conformity.

Asset Optimization Summary

June 8, 2026

AO Corridor	MTP ID	Facility	From	To	Asset Optimization Description
06 - IH 30 West Freeway	FT 28.10.2	IH 30	East of IH 20 (Parker County Line)	Spur 580/Camp Bowie West Blvd	Operational Improvements
06 - IH 30 West Freeway	FT 28.20.3	IH 30	Chisholm Trail Parkway	Henderson Street	Safety Improvements
06 - IH 30 West Freeway	FT 28.20.4	IH 30	Henderson Street	IH 35W	Safety Improvements
07 - IH 35E (Ellis County)	FT 7.100.4	IH 35E	State Loop 9 (Dallas County Line)	US 77 (North of Waxahachie)	Operational Improvements
07 - IH 35E (Ellis County)	FT 7.100.5	IH 35E	US 77 (North of Waxahachie)	Bigham Road (US 77 South)	Operational Improvements, Bottleneck Removal
08 - IH 35W (Tarrant County)	FT 5.70.1	IH 35W	IH 30	Berry Street	Safety Improvements
08 - IH 35W (Tarrant County)	FT 5.70.2	IH 35W	Berry Street	IH 20	Safety Improvements
09 - IH 35W (South)	FT 5.100.2	IH 35W	CR 401	FM 2258	Operational Improvements
10 - IH 45 (Dallas County)	FT 27.20.1	IH 45	US 175	IH 20	Safety Improvements
10 - IH 45 (Dallas County)	FT 27.30.1	IH 45	IH 20	Pleasant Run Rd	Operational Improvements, Bottleneck Removal
10 - IH 45 (Dallas County)	FT 27.30.2	IH 45	Pleasant Run Road	State Loop 9	Operational Improvements, Bottleneck Removal
10 - IH 45 (Dallas County)	FT 27.40.1	IH 45	State Loop 9	South of Malloy Bridge Road (Ellis Co. Line)	Operational Improvements, Bottleneck Removal
11 - IH 45 (Ellis County)	FT 27.40.2	IH 45	South of Malloy Bridge Road (Dallas Co. Line)	BU 45	Operational Improvements
11 - IH 45 (Ellis County)	FT 27.40.3	IH 45	BU 45	SH 34	Operational Improvements
11 - IH 45 (Ellis County)	FT 27.40.4	IH 45	SH 34	US 287	Operational Improvements, Bottleneck Removal
12 - IH 635 (West)	FT 130.10.2	IH 635	Royal Lane	Belt Line Road	Operational Improvements
12 - IH 635 (West)	FT 130.10.3	IH 635	Belt Line Road	PGBT	Operational Improvements, Bottleneck Removal
12 - IH 635 (West)	FT 130.20.1	IH 635	PGBT	West of Luna Road	Operational Improvements, Bottleneck Removal
12 - IH 635 (West)	FT 130.20.2	IH 635	West of Luna Road	IH 35E	Operational Improvements, Bottleneck Removal
12 - IH 635 (West)	FT 130.30.1	IH 635	IH 35E	Webb Chapel Road	Operational Improvements, Bottleneck Removal
13 - IH 820 (West)	FT 153.10.1	IH 820	IH 20	Chapin Road	Operational Improvements
13 - IH 820 (West)	FT 153.10.2	IH 820	Chapin Road	IH 30	Operational Improvements
14 - SH 121 (Tarrant County)	FT 11.100.2	SH 121	Handley-Ederville Road	Beach Street	Operational Improvements
14 - SH 121 (Tarrant County)	FT 11.100.3	SH 121	Beach Street	IH 35W	Operational Improvements, Bottleneck Removal
15 - Southern Gateway	FT 7.90.2	IH 35E	Ann Arbor Avenue	IH 20	Operational Improvements
16 - Spur 408	FT 19.10.1	Spur 408	State Loop 12	IH 20	Operational Improvements, Bottleneck Removal
17 - US 175 (Dallas County)	FT 36.10.2	US 175	Lake June Road	Prairie Creek Road	Operational Improvements

NOTE: Asset Optimization improvements are typically low-cost improvements implemented prior to, or in lieu of, ultimate capacity improvement. These types of improvements are targeted to address location-specific operation, safety, and bottleneck issues within the corridor, and do not affect Transportation Conformity.

Asset Optimization Summary

June 8, 2026

AO Corridor	MTP ID	Facility	From	To	Asset Optimization Description
17 - US 175 (Dallas County)	FT 36.20.2	US 175	Belt Line Road	State Loop 9 (Kaufman County Line)	Operational Improvements, Bottleneck Removal
18 - US 175 (Kaufman County)	FT 36.30.5	US 175	SH 34	FM 2860	Operational Improvements
18 - US 175 (Kaufman County)	FT 36.30.6	US 175	FM 2860	North of Mason Street/ Henderson CL	Operational Improvements
19 - US 287 (North)	FT 1.10.4	US 287	BU 81/Future FM 1810	US 380	Operational Improvements
19 - US 287 (North)	FT 1.20.1	US 287	US 380	BU 81	Operational Improvements
19 - US 287 (North)	FT 1.20.2	US 287	BU 81	FM 407	Addition of Frontage Roads, Operational Improvements
19 - US 287 (North)	FT 1.20.3	US 287	FM 407	North of Pioneer Rd	Operational Improvements
19 - US 287 (North)	FT 1.30.1	US 287	North of Pioneer Road	Ramhorn Hill Road (North of Avondale)	Addition of Frontage Roads, Operational Improvements, Bottleneck Removal
19 - US 287 (North)	FT 1.30.2	US 287	Ramhorn Hill Road (North of Avondale)	South of Ramhorn Hill Road (Tarrant County Line)	Addition of Frontage Roads, Operational Improvements
20 - US 287 (South)	FT 1.60.2	US 287	Sublett Road	Russell Curry Road	Operational Improvements
20 - US 287 (South)	FT 1.60.3	US 287	Russell Curry Road	FM 157	Operational Improvements
20 - US 287 (South)	FT 1.60.4	US 287	FM 157	Walnut Creek Drive	Operational Improvements
20 - US 287 (South)	FT 1.70.1	US 287	Lone Star Road	East of Lone Star Road (Ellis County Line)	Operational Improvements, Addition of Frontage Roads
20 - US 287 (South)	FT 1.80.1	US 287	East of Lone Star Road (Johnson County Line)	St Paul Road	Operational Improvements, Addition of Frontage Roads
20 - US 287 (South)	FT 1.100.1	US 287	US 67	Midlothian Pkwy	Addition of Frontage Roads, Operational Improvements
20 - US 287 (South)	FT 1.100.3	US 287	BU 287 (West of Waxahachie)	IH 35E	Operational Improvements
20 - US 287 (South)	FT 1.120.1	US 287	BU 287 (West Ennis)	Lampasas Road	Addition of Frontage Roads
21 - US 67 (Johnson County)	FT 38.60.2	US 67	BU 67/SS 102	SH 174	Addition of Frontage Roads
22 - Woodall Rodgers	FT 44.10.1	Spur 366	US 75	IH 35E	Operational Improvements, Bottleneck Removal

NOTE: Asset Optimization improvements are typically low-cost improvements implemented prior to, or in lieu of, ultimate capacity improvement. These types of improvements are targeted to address location-specific operation, safety, and bottleneck issues within the corridor, and do not affect Transportation Conformity.